




## North Bay-Mattawa Watershed Report Card 2018

Subwatershed	Stream Water Quality A	Lake Water Quality B+	Groundwater Quality A	Forest Cover Overall A	Wetland Cover B
Amable du Fond River	A	Kawawaymog Lake - A Smith Lake - A		A	C
Boom Creek				A	A
Burford Creek	C			A	A
Callander Bay/South Shore	D	Callander Bay - B		A	A
Chippewa Creek	C		Well 277 - A	B	B
Duchesnay Creek	B	Four Mile Lake - A		A	A
Jessups Creek				A	A
Kaibuskong River	A	Lake Nosbonsing - B		A	B
La Vase River				A	A
Lake Nipissing North Bay				C	A
Lake Talon		Lake Talon - B		A	C
Mattawa River	A	Earls Lake -B		A	D
North River				A	C
Parks Creek			Well 274 - A	B	A
Pautois Creek		Papineau Lake - B		A	B
Sharpes Creek			Well 391 - A	A	B
Trout Lake	A	Trout Lake - A	Well 392 - A	A	C
Turtle Lake		Turtle Lake - A		A	B
Windsor/Boulder/Bear Creeks	C			A	A
Wistiwasing River	C	Wasi Lake - C		A	A

Data Not Collected  
or Insufficient Data

See Subwatershed Map Below



Produced by NBMCA GIS Services. [2018]  
 © Queen's Printer for Ontario and its licensors. [2018]  
 May Not be Reproduced without Permission.  
**THIS IS NOT A PLAN OF SURVEY**